IN THE UNITED STATES DISTRICT COURT FOR THE WESTERN DISTRICT OF WISCONSIN

BAD RIVER BAND OF THE LAKE SUPERIOR TRIBE OF CHIPPEWA INDIANS OF THE BAD RIVER RESERVATION,

Plaintiff,

v.

ENBRIDGE ENERGY COMPANY, INC., and ENBRIDGE ENERGY, L.P.,

Defendants.

ENBRIDGE ENERGY COMPANY, INC., and ENBRIDGE ENERGY, L.P.,

Counter-Plaintiffs,

v.

BAD RIVER BAND OF THE LAKE SUPERIOR TRIBE OF CHIPPEWA INDIANS OF THE BAD RIVER RESERVATION and NAOMI TILLISON, in her official capacity,

Counter-Defendants.

Case No. 3:19-cv-00602-wmc

Judge William M. Conley Magistrate Judge Stephen L. Crocker

JOINT STATUS REPORT REGARDING MEANDER CONDITIONS

Plaintiff and Defendants (collectively, the "Parties") jointly submit this status report, and state the following:

The Parties submit this status report to apprise the Court of conditions at the Bad River meander (the "Meander"). The facts contained herein are accurate as of Friday, April 28, 2023. The Parties will provide updates to the Court as warranted.

Under current conditions known to the Parties, neither Enbridge's current Monitoring, Shutdown, and Purge Plan (the "Plan" filed at Dkt. 616-1) nor Enbridge's proposed plan (Dkt. 616-2), nor the Band's most recent proposed plan (Dkt. 617) requires a shutdown or purge at this time. Enbridge represents that it has kept PHMSA informed of the conditions at the Meander.

Enbridge represents that, in advance of the Spring flooding season, it installed 21 new monuments in addition to the 14 original monuments that were already installed, as well as additional cameras in the area.

The Bad River overtopped its banks at the Meander the past two weekends. *See* **Figure 1**, below.



Figure 1. Bad River Inundation of Meander Neck, April 14, 2023 (View East).

(Source: Enbridge drone photograph, taken 4/14/23, file DJI_0373.JPG)

As described below there has been a loss of bank separating Line 5 from the Bad River in certain areas. At the time of trial, the pipeline was roughly 26.5 feet from the bank of the Bad River at the closest point. The shortest distance between the pipeline and the River is now roughly 17–18 feet.

Beginning Sunday, April 9, warm weather caused the snowpack in the Bad River watershed to melt, resulting in significant runoff. The river overtopped the neck of the Meander on Tuesday, April 11. The river rose steadily, reaching its maximum height on Thursday, April 13, with flows measured at 13,900 cubic feet per second (cfs), corresponding to approximately a 10-year event. On Sunday, April 16, a spring storm brought additional precipitation, contributing additional runoff.

The flood levels began to recede on Monday, April 17. With additional precipitation in the watershed on Thursday, April 20, and Friday, April 21, the flows in the Bad River again rose. On April 21 the Bad River again overtopped its banks, with river flows peaking at 10,400 cfs, reflecting less than a 5-year event. The flood waters receded below the top of the bank at the Meander two days later, on the morning of Sunday, April 23.

Between April 11 and April 23, the Bad River was out of its banks at the Meander for a total of 9 days. When the River was out of its banks, or when flood waters were receding, some monuments marking the distance between Line 5 and the Bad River fell due to erosion of the underlying soils, while others were knocked over by floating debris even though the bank/earth underneath remained in place. A schematic that depicts the monuments and the locations of the lost or knocked over monuments is below at **Figure 2**.

Line 5 Monuments Cameras Approximate edge of bank from 4/29 drone image 23-24 ft at M3 series 17-18 ft at F series 25-26 ft at M2 series CAM5 CAM-R2 Bank lost at these monument locations between April 11 and April 23 CAM-R3 Niswi camera out of frame 10 20 40 Feet


Figure 2. Map of Lost Monitoring Monuments at the Bad River Meander

The Band has reported that one of its tree-fixed cameras monitoring the river and the monuments was lost during the flooding. While Enbridge has access to the imagery from the Band's cameras, imagery from this camera is not used by Enbridge as part of its monitoring efforts in accordance with its Plan, and is monitored only by the Band. Enbridge's cameras are in place and functioned as intended during this high flow event.

The Bad River waters have now receded. During the past two weeks, approximately 10 feet of bank has been lost at the M3 series of monuments, 1–2 feet at the M2 series, 8 feet at the F series, and no bank loss was observed at the J series. There has also been bank loss at the E and D series, but the Parties have not yet quantified the precise footage of bank loss along the E and D series but the Parties agree the bank in those locations is farther away from the pipeline than the bank at the F series monuments, as discussed immediately below. *See* **Figure 3.** The exact conditions at each monument series will be confirmed once an in-person joint site visit occurs.


Figure 3. Ground-Level Camera Images Showing Meander Neck Bank Erosion and Lost Monuments from April 12, 2023, to April 26, 2023 (View East).

April 12, 2023:



(Photo source: Enbridge Camera 4, taken 4/12/23 at 11:56 CDT. Annotations added by Ian Paton.)

April 26, 2023:



(Photo source: Enbridge Camera 4, taken 4/26/23 at 11:46 CDT. Annotations added by Ian Paton.)

The pipeline is closest to the edge of the riverbank at the F series of monuments, where the remaining distance now stands at approximately 17–18 feet. On February 8 of this year,

Enbridge and the Band had measured the distance between the pipe and the bank at that location at approximately 25 feet, meaning that approximately 7.5 feet of bank has been lost at that location in the intervening time period. *See* **Figure 4.** Additional sloughing of the bank is possible depending on a variety of factors. *See id.*

F-series monuments

Line 5 alignment (approximate)

17-18 ft estimated distance from Line 5 to bank

Monument F3 (15 ft from Line 5)

Exposed tree roots

Figure 4. Aerial Image of Meander Neck, April 26, 2023 (View North).

(Photo source: Screenshot from drone video collected by Band contractor on 4/26/23. ["bad River 4 26 23 Flight 1.m4v", time 05:44]. Annotations added by Ian Paton.)

Throughout the high-flow events, the Parties have been and remain in close communication, sharing imagery, forecasts, and interpretations of the data at least daily. The Parties are coordinating a joint in-person field visit to occur as soon as safe and feasible in order to further assess the conditions at the Meander and to inspect and, as necessary, re-affix monitoring equipment to the riverbank. The Parties expect that this visit will occur within the next two weeks.

The Parties are continuing discussion of the issues raised in the Court's order of November 28, 2022 (Dkt. 612), as referenced in the Parties' Joint Status Report of December 23, 2022 (Dkt. 614).

If at any time the Court has any questions about the significance or materiality of the information presented in this joint status report, the Parties are available at the Court's convenience and would appreciate the opportunity to respond to, address, and/or present legal argument regarding any such questions.

Dated: May 01, 2023

/s/ Riyaz A. Kanji
Riyaz A. Kanji
David A. Giampetroni
Lucy W. Braun
Christopher Miller
KANJI & KATZEN, P.L.L.C.
303 Detroit Street, Suite 400
Ann Arbor, MI 48104
rkanji@kanjikatzen.com
dgiampetroni@kanjikatzen.com
lbraun@kanjikatzen.com
cmiller@kanjikatzen.com
(734) 769-5400

Jane G. Steadman
Philip H. Tinker
Claire R. Newman
KANJI & KATZEN, P.L.L.C.
811 1st Avenue, Suite 630
Seattle, WA 98104
jsteadman@kanjikatzen.com
ptinker@kanjikatzen.com
cnewman@kanjikatzen.com
(206) 344-8100

Erick Arnold
BAD RIVER BAND OF THE LAKE SUPERIOR
TRIBE OF CHIPPEWA INDIANS OF THE BAD
RIVER RESERVATION
72682 Maple Street
Odanah, Wisconsin 54861
attorney@badriver-nsn.gov
(715) 682-7107

Bruce Wallace HOOPER HATHAWAY PRICE BEUCHE & WALLACE 126 S. Main Street Ann Arbor, MI 48104 bwallace@hooperhathaway.com (734) 662-4426 Respectfully submitted,

/s/ Michael C. Davis
Michael C. Davis
David L. Feinberg
Justin B. Nemeroff
Venable LLP
600 Mass. Ave., NW
Washington, D.C. 20001
(202) 344-8278
MCDavis@venable.com
DLFeinberg@venable.com
JBNemeroff@venable.com

David H. Coburn Shannen W. Coffin Steptoe & Johnson LLP 1330 Connecticut Avenue, NW Washington, DC 20036-1795 (202) 429-8063 dcoburn@steptoe.com scoffin@steptoe.com

Eric M. McLeod Joseph S. Diedrich Husch Blackwell 33 East Main Street, Suite 300 Madison, WI 53701-1379 (608) 234-6056 eric.mcleod@huschblackwell.com

Counsel for Defendants

Oday Salim NATIONAL WILDLIFE FEDERATION 213 West Liberty Street, Suite 200 Ann Arbor, MI 48104 salimo@nwf.org (586) 255-8857

Douglas M. Poland David P. Hollander STAFFORD ROSENBAUM, LLP 222 West Washington Avenue, Suite 900 Madison, WI 53701 dpoland@staffordlaw.com dhollander@staffordlaw.com (608) 256-0226

Counsel for Plaintiff and Naomi Tillison, Director of the Mashkiiziibii Natural Resources Department of the Bad River Band, in her official capacity

CERTIFICATE OF SERVICE

I certify that on May 01, 2023, this document was served on all parties or their counsel of record through the CM/ECF system if they are registered users or, if they are not, by placing a true and correct copy in the United States mail, postage prepaid, to their address of record.

/s/ Riyaz A. Kanji Riyaz A. Kanji